Notice



CORRECTION PRODUCTION C	CHANGE
SERVICE FLASH ADD INFORMAT	FILE NO.
Please add this notice to the Service M	anual listed below. REVISION 0
Category: COLOR TELEVISION	Date: FEBRUARY / 07 / 2012
Model: DP46861	Effective from : Chassis No. P46861-11
Destination: U.S.A. / CANADA REF : No. SM780195-11	
	it's back cover with the Chassis No. in the Service
	ssis No. does not match the unit's, additional Service sis is similar to Chassis No. P46841-10. Only the

SERVICING SHOULD BE PERFORMED BY ONLY TRAINED AND QUALIFIED SERVICE PERSONNEL.

difference Service Information is given in this manual. For detailed Service Information, refer to the **Original** Service Manual for Chassis No. and **Notices** for Chassis No. P46841-

1. IN THE SERVICE ADJUSTMENTS

The are no changes.

2. IN THE CHASSIS ELECTRICAL PARTS LIST MISCELLANEOUS

10 used in Model DP46841 (SM780195).

The are no changes.

3. PWR ON LED POSITION CHANGE

Before (Z5WM): Right side Current (Z5WME): Left side

For parts or service contact:

Sanyo Manufacturing Corporation P.O. Box 2000 3333 Sanyo Road Forrest City, Arkansas 72335-2000

February 2012 SMC

Sanyo Manufacturing Corporation 2012